



472813



3

Removal Area 7: looking upstream, Fall 2012



4

Removal Area 7: looking downstream, Fall 2012

GEORGIA-PACIFIC LLC
ALLIED PAPER, INC/PORTAGE CREEK/
KALAMAZOO RIVER SUPERFUND SITE
FORMER PLAINWELL IMPOUNDMENT AND PLAINWELL NO. 2 DAM AREA SPRING
2012 BANK CONDITIONS MONITORING REPORT

**FORMER PLAINWELL IMPOUNDMENT REMOVAL
AREAS 7, 8, and 9B - PHOTOLOG**



Figure 1



1

Removal Area 7: looking upstream, Spring 2012



2

Removal Area 7: looking downstream, Spring 2012

GEORGIA-PACIFIC LLC
ALLIED PAPER, INC/PORTAGE CREEK/
KALAMAZOO RIVER SUPERFUND SITE
FORMER PLAINWELL IMPOUNDMENT

**FORMER PLAINWELL IMPOUNDMENT REMOVAL
AREAS 7, 8, and 9B - PHOTOLOG**



Figure
1



7

Removal Area 8: looking downstream, Fall 2012



8


Removal Area 8: looking downstream, Fall 2012

GEORGIA-PACIFIC LLC
ALLIED PAPER, INC/PORTAGE CREEK/
KALAMAZOO RIVER SUPERFUND SITE
FORMER PLAINWELL IMPOUNDMENT AND PLAINWELL NO. 2 DAM AREA SPRING
2012 BANK CONDITIONS MONITORING REPORT

**FORMER PLAINWELL IMPOUNDMENT REMOVAL
AREAS 7, 8, and 9B - PHOTOLOG**



Figure 1



5

RA-8: Looking upstream, Spring 2012



6

Removal Area 8: looking upstream, Fall 2012

GEORGIA-PACIFIC LLC
ALLIED PAPER, INC/PORTAGE CREEK/
KALAMAZOO RIVER SUPERFUND SITE
FORMER PLAINWELL IMPOUNDMENT AND PLAINWELL NO. 2 DAM AREA SPRING
2012 BANK CONDITIONS MONITORING REPORT

**FORMER PLAINWELL IMPOUNDMENT REMOVAL
AREAS 7, 8, and 9B - PHOTOLOG**



Figure 1



11

Removal Area 9B: looking upstream, Fall 2012



12

Removal Area 9B: looking downstream, Fall 2012

GEORGIA-PACIFIC LLC
ALLIED PAPER, INC/PORTAGE CREEK/
KALAMAZOO RIVER SUPERFUND SITE
FORMER PLAINWELL IMPOUNDMENT AND PLAINWELL NO. 2 DAM AREA SPRING
2012 BANK CONDITIONS MONITORING REPORT

**FORMER PLAINWELL IMPOUNDMENT REMOVAL
AREAS 7, 8, and 9B - PHOTOLOG**



Figure 1



9

RA-9B: looking upstream, Spring 2012



10

Removal Area 9B: looking upstream, Fall 2012

GEORGIA-PACIFIC LLC
ALLIED PAPER, INC/PORTAGE CREEK/
KALAMAZOO RIVER SUPERFUND SITE
FORMER PLAINWELL IMPOUNDMENT AND PLAINWELL NO. 2 DAM AREA SPRING
2012 BANK CONDITIONS MONITORING REPORT

**FORMER PLAINWELL IMPOUNDMENT REMOVAL
AREAS 7, 8, and 9B - PHOTOLOG**



Figure 1